

# WATER QUALITY DOCUMENTS

Well and Septic System Document Image Availability

# SCANNING PROJECT

- In March to July 2019, the Public Health Department entered into a project with a vendor to scan and index the approximate 70,000 hardcopy Well and Septic permit and support documents managed by the Water Quality group of the Environmental Health Division.
- The documents involved in this project were the working documents obtained from permits and inspections that occurred from 1980 until 2019.
- Permits and inspections older than 1980 will be scanned at a later date and are currently available for review in the Water Quality office.




## IMAGE AVAILABILITY

The digital documents are associated with the individual parcel record as shown in the image to the right.

If a parcel record has a 'Water Quality' hyperlink, then it has documents available for viewing. Clicking this link will provide access.

The individual parcel record can be accessed by using the **Search** or **Identify** tools in the application.



The screenshot displays the GIS Data Viewer interface. The left sidebar shows the 'Identify' tool selected, displaying the following information for a parcel:

**GUILFORD COUNTY**  
3441 NORTHEAST PARK DR

[Property Report](#) [Community Info](#)  
[Sales History](#) [Water Quality](#)  
[Oblique Photos](#)

|                          |                                 |
|--------------------------|---------------------------------|
| Parcel Number            | 101954                          |
| PIN                      | 8828019610                      |
| Owner History            | <a href="#">Card Image</a>      |
| Owner                    | GUILFORD COUNTY                 |
| Mail Address             | PO BOX 3427                     |
| Mail City                | GREENSBORO                      |
| Mail State               | NC                              |
| Mail Zip                 | 27402                           |
| Property Address         | 3441 NORTHEAST PARK DR          |
| Legal Description        | 369.40AC NORTHEAST PARK PHASE I |
| Deed                     | <a href="#">005428-01627</a>    |
| Plat                     |                                 |
| Condo                    |                                 |
| Total Assessed           |                                 |
| Total Building Value     | 0                               |
| Total Out Building Value |                                 |
| Total Land               |                                 |

The right side of the interface shows a satellite map with yellow parcel boundaries. A red arrow points from the 'Water Quality' link in the sidebar to a specific parcel on the map.

PROPERTY SERVICE CHART

ADDRESS

| SERVICE | COMMENTS | DATE | REHS |
|---------|----------|------|------|
|         |          |      |      |
|         |          |      |      |
|         |          |      |      |
|         |          |      |      |
|         |          |      |      |
|         |          |      |      |
|         |          |      |      |
|         |          |      |      |
|         |          |      |      |

GCGD223--10/92

PROPERTY SERVICE CHART

204276

4208 Aberdare Dr. S/T Permit: \_\_\_\_\_ Date: \_\_\_\_\_  
 ADDRESS (Print) Name: \_\_\_\_\_  
 Well Permit: \_\_\_\_\_ Date: \_\_\_\_\_  
 Subd: \_\_\_\_\_ Sec. \_\_\_\_\_ Lot \_\_\_\_\_ Name: \_\_\_\_\_

| SERVICE   | COMMENTS   | DATE     | SANITARIAN |
|-----------|--|----------|------------|
| Septic ✓  | Proposed structure 83' from SFR; over 100' from well. Possible malfunction on septic line, wet spot w/ no rain lately. Gave to JAE to check out. | 12/8/00  | swr        |
| Site work | w/owner system is not surfacing, vegetation shows wetness - soil is very poor "U" released   |          |            |
|           | shall- issued permit for repair during dry season of 2001  | 12/13/00 | FAE        |
|           | pre-install required   | 1/17/01  | FAE        |
| Site work | w/owner no surfacing   | 5/28/02  | FAE        |
|           |  |          |            |
|           |  |          |            |
|           |  |          |            |
|           |  |          |            |
|           |  |          |            |
|           |  |          |            |

DOCUMENT DETAIL

When the hyperlink is clicked, a PDF file will open in a new browser tab.

The first two (or more) pages will always be the 'Property Service Chart'. These pages act as an activity log to document past and future work performed on this parcel.

Other pages may include various permits, maps and other supporting documentation.

# QUESTIONS

- For questions regarding permit data, please contact the Water Quality Division at (336) 641-7613 or by email [waterquality@guilfordcountygis.gov](mailto:waterquality@guilfordcountygis.gov).
- Please visit their [website](#), for additional information.
- For questions regarding the operation of the GIS Data Viewer in general, please contact the GIS Division at (336) 641-7583 or by email at [gis@guilfordcountync.gov](mailto:gis@guilfordcountync.gov)